# Office of the District Fire Officer Karnataka State Fire and Emergency Services Khanapur Road, Belagavi-590001



Phone: 0831-2429441 E-Mail: dfobgv@gmail.com

Date: 05-11-2024

### C.NO/234/FSCR/DFO/BELAGAVI/2022

To. The Chairman Shri S.M.Naragond International School, Harugeri Raibag Taluk, Belagavi District.

Sir.

Sub: Issue of 'Fire Safety Compliance Report' to Shri Mallikarjun

Foundation's, Shri S.M.Naragond International School, Harugeri, Raibag

Taluk, Belagavi District.

Ref: 1) C.NO/234/ADV/DFO/BELAGAVI/2022

Date: 26-09-2022.

2) Applicant Request Letter

Date: 23-09-2024.

With reference to the subject above cited, the premises of Shri Mallikarjun Foundation's, Shri S.M.Naragond International School, building consisting with Ground and 2 Upper floor situated at Harugeri, Raibag Taluk, Belagavi District was inspected by District Fire Officer, Belagavi on 01/10/2024 with respect to fire Prevention, Fire Fighting & Evacuation point of view for the purpose of issuing FSCR and the details as under.

### ANNEXURE-1

(Up to 14.99 mtrs. In height)

# "GROUP-B Educational Buildings

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory.)

01	Name and Address of the Applicant	The Chairman			
		Shri S.M.Naragond			
	3 3	International School, Harugeri			
		Raibag Taluk, Belagavi District.			
02	Name and Address of the Premises	Shri Mallikarjun Founadtion's			
-		Shri S.M.Naragond			
		International School, Harugeri			
		Raibag Taluk, Belagavi District.			
03.	Name and Address of the Building	The Chairman			
	Owner	Shri Mallikarjun Founadtion's			
		Shri S.M.Naragond			
		International School, Harugeri			
		Raibag Taluk, Belagavi District.			
04.	Number of Building	01			
05.	Number of Floors	G+2			
06.	Floorwise details of Accupancy:-				
	Ground Floor	Class Room-11, Principal Chamber-01,			
		Management Room-01 & Store Room-01			

	1 <sup>st</sup> floo	r   Class Room-13, Computer Lab-03, Librotary				
		01, Library-01, Music Room-01 & Store				
		Room-01.				
	2 <sup>nd</sup> floo	r Class Room-16, Multipurpose Hall-01, Art				
07.	Heister Color	Room-01 & Store Room-01				
07.	Height of the building	10.80 mtr				
08.	Site area	4 Acre 4 Gunta				
09.	Built-up area of each floor:-					
	Ground Floor	1994.33 Sq mtr				
	1 <sup>st</sup> floor	1994.33 Sq mtr				
• •	2 <sup>nd</sup> floor	1994.33 Sq mtr				
10.	Total Built-up area	5982.99 Sq mtr				
11.	Surrounding properties:-	oq mu				
	East	Road				
	West	Agriculture Land				
	North	Agriculture Land				
	South	Agriculture Land				
12.	Open Space all around the building	C Sant Danie				
	East	Ground Nil				
	West					
	North	02.00 mtr 19.90 Mtr				
	South					
	Allowed Setbacks (open space) shoobstruction/construction.	ald be maintained for a factor				

# B. On the inspection of this School/College premises, the following Fire Prevention, Fire Fighting and Evacuation Measures recommended are considered absolutely essential from fire safety point of view:-

Sl. No (01)	Details (02)	I	Existing (03)	Recommendation (04)		
01.	Accessibility to the premises	The premises 12.00 Mtr wid Side	is accessible from e road on the Eastern	Adequate		
02.	Number of Entrances	01 no. Of 10 side.	mtr wide on Eastern	Adequate		
03.	Number of Staircase	No of staircase	04 nos. all are equal measuring	Complied		
		Width of the staircase	1.50 mtr	# desta		
		Width of threads	0.30 cms	and and all		
		Height of risers	0.15 cms			
		No of risers per flight	10	(320,380)		

		Height of the hand drill.	
4.	Portable	12 Nos. of 04 kg capacity ABC type	
	Extinguishers	extinguisher & 01 CO2 has been	Complied.
		provided extinguisher.	
		All the extinguishers suggested are	
		BIS markings and are located at an	
		Bis markings and are located at an	
		easily accessible position without	
		obstructing the normal passage.	
05.	Hose reel hose	Six Hose reel hose has been	
	system	provided near the staircase (One	
		hose reel hose system for every	Complied.
		1000 sq.mtrs). The hose reel hose	Complica
		of min 19 mm size and of 30 mtrs	90 .
		length to reach the farthest point of each floor and shut off branch	c
		having a nozzle of 05 mm size.	
01	At the termone	The system ha been connected to	Complied.
06.	At the terrace tank level with	an booster pump of 450 LPM or of	A management
	minimum	5 HP capacity.	
	pressure of 3.5	Further the system should be	
	kg/cm2	connected to an alternative source	
	Kg/CIII2	of power supply.	
07.	Diesel	01 no. Of 15 KVA generator	Complied.
	Generator	provided.	
08.	Terrace Tank	The system has been connected to	Complied.
		an 2 Nos. of over head tank each of	
		10000 ltrs capacity.	
09.	Escape routes	Direction in which the students	
	-	have to move in the event of an	Complied.
		emergency has been displayed in	2
		the corridor on each floor during	
		evacuation.	
10.	Fire Order	A notice board indicating the action	b2
	(Fire safety	to be taken by the employees in	Access to
	plans)	case of any emergency has been	Complied.
		displayed with the telephone numbers of Raibag fire station i,e	
		08331-224101 & 101, 080-	13250
		22971550, 22971500, 22971600	* क्रिक्टिश्चर
		and the telephone nos nearest	3
		ambulance services and police	30 26 2 0
		station, to each block.	
11.	No Smoking	COPTA Sec-4 direction of No	
11.	board	Smoking area, smoking here is an	Complied.
		offence board should be written in	March 1
		English & Kannada both languages	
		shall be prominently displayed at	
		inside the entry/exit of the each	
		floor, to each block.	
12.	Fire Siren	A Fire Siren has 0. be installed in	
-	processings (SPANSONSWIEW)	the premises to inform the inmates	

13.	Name of Co.	in case of a fire emergency and evacuate the area.	Complied.			
	Nominate One Fire Nodal Officer	Shri Bahuballi Siddappa Naganur Shri Suprit Prakash Noginhal have been nominated as the Fire Nodal Officer.	Complied.			
14.	Fire Fighting Training	Not Imparted	At least 40% of the Teaching and non Teaching staff should be go trained in basic fire fighting at R.A.Mundkur Fire & Emergency Services Academy, Bannerughatta Road, Bangalore or Regional training centre.			

A:- Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.

B:- Accumulation of combustible waste in and around the premises should be avoided.

C:- The Exit ways shall be always kept clear without any obstruction. D:- Liquefied petroleum gas should not be stored in the building.

E:- The doors shall not be kept locked latched during working hours and shall be free from obstruction.

F:- During the class hours the class room door shall not be locked from inside to out side.

G:- As per Honorable Supreme Court order all teachers and staff shall be trained to handle safety equipments, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year by conducting Fire Safety drills with co-ordination

Under the above circumstance the Karnataka Fire & Emergency Services Department is issuing "Fire Safety Compliance Report" to the Shri Mallikarjun Foundation's, Shri S.M.Naragond International School, Harugeri, Raibag Taluk, Belagavi District. As they have complied all the recommendations as per reference 1. The staff should get trained in the basic fire fighting at R.A.Mundkur Fire & Emergency Services Academy, Bannerughatta Road, Bangalore or Regional training centre Hubballi.

This "FSCR" is valid for only one year from the date of issue and is renewable.

Yours Faithfully

Karnataka State Fire And Emergency Services

Belagavi-01.

Date: 05-11-2024

### FIRE SAFETY CERTIFICATE

No: 234/FSCR/DFO/BELAGAVI/2022

Certified that the Shri Mallikarjun Foundation's, Shri S.M.Naragond International School, Harugeri, Raibag Taluk, Belagavi District. Comprised of Zero Basement, Ground & Two Upper Floors Owned/Occupied by Shri S.M.Naragond International School, have complied with the fire prevention and fire safety requirements in accordance with rule of State/UT Fire Service Rules, and verified by the District Fire Officer Belagavi Fire Service on 01-10-2024 in the presence of The Principal, Sri. Prashant L.H. and that the Building/Premises is fit for occupancy upto classes Xth with effect from 05-11-2024 for a period of Two Years in accordance with rule and subject to compliance of specific conditions as appended:-

- 1. Maintenance of all fire fighting installations periodically
- 2.
- 3.
- 4.

## Issued on 05-11-2024 at Belagavi, by

\*Strike out whichever is not applicable.

To,
The Chairman
Shri S.M.Naragond
International School, Harugeri
Raibag Taluk, Belagavi District.

Karnataka State Fire And Emergency Services

Signature with Seal : ......Belagavi-01.....

Name : <u>S.S.Nilgar</u>

Designation : District Fire Officer

Name & Address

of Department/Office: Office of the District Fire Officer

Karnataka State Fire & Emergency Services, Khanapur Road, Near Goaves Circle, Belagavi-590001.

### **ENDORSEMENT**

Th	e No Ob	jection	Certific	ate issue	ed by 1	Fire S	ervice	stand	canc	elled a	n ann	ılled dı	ie to
									•••••	• • • • • • •			
				• • • • • • • • • • • • • • • • • • • •					• • • • • •	•••••	• • • • • • • • • • • • • • • • • • • •	•••••	

(Name and Designation of the authorized signatory)

\*The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with original vernacular certificate as a single pdf.